

|                |                                     |                     |                   |
|----------------|-------------------------------------|---------------------|-------------------|
| Cartype:       | Nissan Infiniti FX30d (2010 – 2013) | VIN:                | SJKDBNH15U1029676 |
| License plate: | PB8443TT                            | Km-Stand abgelesen: | 101940 km         |

Safety-related control units:

|   | System             | ECU Name      | Status |
|---|--------------------|---------------|--------|
| ❗ | Engine electronics | ECM_C_default | Error  |

Non-safety-related control units:

|   | System                   | ECU Name      | Status |
|---|--------------------------|---------------|--------|
| ✅ | Transmission electronics | TCM_C_Default | OK     |

Remarks:

Inspector: Signature:

---

|                       |                                     |                            |                   |
|-----------------------|-------------------------------------|----------------------------|-------------------|
| <b>Cartype:</b>       | Nissan Infiniti FX30d (2010 – 2013) | <b>VIN:</b>                | SJKDBNH15U1029676 |
| <b>License plate:</b> | PB8443TT                            | <b>Km-Stand abgelesen:</b> | 101940 km         |

---

## Engine electronics (ECM\_C\_default)

### Identification:

VIN: SJKDBNH15U1029676      AVL-ECU-ID: 3680-3710-7

### Error Codes:

| Error code   | Error description                                    |
|--------------|------------------------------------------------------|
| [200A] P200A | Intake Manifold Runner Bank 1 Performance Error      |
| [0299] P0299 | Turbocharger/Supercharger "A" - Underboost Condition |

---

## Transmission electronics (TCM\_C\_Default)

### Identification:

VIN:      AVL-ECU-ID: 3678-2318-1

### Error Codes:

No error found.

---

---

### Remarks:

---

Inspector:

Signature:

---

---